

Division of Oil, Gas, & Mining
Mining Report

09/26/95

MINE ID: S0530010

MINE NAME: BEAVER DAM WASH

OPERATOR: BARRETT MINES INCORPORATED

CONTACT: ROBERT R ROBISON

ADDRESS: 14 SHAW DRIVE
BROWNWOOD TX 76801

PHONE: (915)646-5751

Surface Owner: STATE

BLM #:

Mineral Owner: STATE

Lease #: 42979

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	SE	NW				16	40.0S	19.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: SUS

Acreage: 5

Status Date: / /

Minerals Mined
AU, AG

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

07/19/89

/ /

09/28/89

09/13/95

BOND TYPE: N/A

BOND AMOUNT:

ANNUAL REPORT YEAR: 90

	YTD	Total				
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /

COMMENTS:

MINE LOCATED 1/2 MILE NE OF TOWN OF MOTOQUA. NO EVIDENCE OF MINE DISTURBANCE AT 1992 INSPECTION. ACCESS ROAD CONSTRUCTED IN 1990 SHOWED NO OBVIOUS CHANGE SINCE LAST INSPECTION 10/91. MR. BARRETT HAS BEEN SUBPOENAED BY THE BLM AND AFTER SUBSEQUENT SENTENCING, HAS ARRANGED TO HAVE HIS CONTRACTOR PERFORM RECLAMATION WORK ON PUBLIC LANDS. BLM IS NOT SATISFIED WITH WORK DONE. INSPECTION OF 9/95 STATES AFTER RECLAMATION IS COMPLETED, FILE COULD POSSIBLY BE CLOSED.